


1. TO INSPECT ASSEMBLY, FOLLOW FIRST ARTICLE AND IN PROCESS INSPECTION SHEET.

BILL OF MATERIAL (CURRENT LEVEL)

ITEM	PT/ASSY	DESCRIPTION	TYPE	QTY.
1	5-034	AIR GAP BODY	ASSEMBLY	1
2	3310-5751	-	ASSEMBLY	1



		-	-
TESTING	-	-	-
ASSEMBLY	-	-	-
PLATING	-	-	-
POLISHING	-	NEXT ASSY	USED ON
MACHINING	-	APPLICATION	
TOOLING FIXTURE #		REMOVE ALL BURRS AND SHARP EDGES	

TOLERANCES ARE:

FRACTIONS DECIMALS	ANGLES
$\pm 1/16"$	$\pm 1^\circ$

$\bar{X} \pm 1$	(2,5)
$\bar{X} \pm 0.6$	(1,5)

X.XXX DENOTES CRITICAL DIMS.
ALL THREADS ARE CRITICAL

DRAWN

G.B.

12/06/20

CHECK

LM

13/06/20

BRASSTECH
INCORPORATED

2001 CARNEGIE AVE.
SANTA ANA, CA 92705
(949) 417-5207

AIR GAP ASM

DWG NO.	
---------	--

3310-5711

RE

SCALE 400

REF.	-
------	---

SHEET	OF	
-------	----	--

COPYRIGHT 2005 BRASSTECH, INC.
THESE DRAWINGS AND THE DESIGNS
DEPICTED HEREIN ARE THE PROPRIETARY
PROPERTY OF BRASSTECH. ANY USE
OR REPRODUCTION IS SUBJECT TO
THE EXPRESS APPROVAL OF BRASSTECH.
UNAUTHORIZED USE IS STRICTLY
PROHIBITED. ALL RIGHTS RESERVED.

-	-	EN-4290	12/06/20	J.M.
ZONE	REV	DESCRIPTION	DATE	APPROVED