


NOTES:


1. TO INSPECT ASSEMBLY, FOLLOW FIRST ARTICLE AND IN PROCESS INSPECTION SHEET.

2. APPLY LOCTITE 680.



BILL OF MATERIAL (CURRENT LEVEL)

ITEM	PT/ASSY	DESCRIPTION	TYPE	QTY.
1	CB-001	LIGHT MOUNTING KIT	ASSEMBLY	1
2	3681-LB	BASE	PART	1
3	3681-BAW	BODY ASSEMBLY	ASSEMBLY	1
4	92819	NUT, M18 X 1.5 MM HEX EXTRA THIN BRASS	PART	1
5	3681-G-0	SHADE ASSEMBLY	ASSEMBLY	1
6	98006	LABEL, UL LISTED	PART	1
7	98079	LABEL, MONTH YEAR E222146	PART	2
8	98012	LABEL, WALL MOUNT ONLY	PART	1
9	98101	LABEL, 100 WATTS MAX	PART	1
10	98113	LABEL,PNXXX INCANDESCENT FOR DAMP LOCATIONS	PART	1
11	98088	LABEL, MIN 75 C SUPPLY CONDUCTORS	PART	1




ZONE	REV	DESCRIPTION	DATE	APPROVED
-	D	EN-4300o	06/10/21	R.S.
-	C	EN-3127	08/29/16	R.S.
-	B	EN-2574	08/06/13	-
-	A	EN-2231	03/25/13	-
-	-	EN-1674	06/08/11	-


COPYRIGHT 2005 BRASSTECH, INC. THESE DRAWINGS AND THE DESIGNS DEPICTED HEREIN ARE THE PROPRIETARY PROPERTY OF BRASSTECH. ANY USE OR REPRODUCTION IS SUBJECT TO THE EXPRESS APPROVAL OF BRASSTECH. UNAUTHORIZED USE IS STRICTLY PROHIBITED. ALL RIGHTS RESERVED.

TESTING	-	-	-
ASSEMBLY	-	-	-
PLATING	-	-	-
POLISHING	-	NEXT ASSY	USED ON
MACHINING	-	APPLICATION	
TOOLING FIXTURE #	REMOVE ALL BURRS AND SHARP EDGES		

UNITS ARE: INCHES [MM]	
TOLERANCES ARE:	
FRACTIONS DECIMALS ANGLES	
±1/16" .X ±.1 [2.5] ±1°	
.XX ±.06 [1.5]	
(X.XXX) DENOTES CRITICAL DIMS.	
ALL THREADS ARE CRITICAL	
DRAWN JINSON	06/10/21
CHECKED R.S.	06/10/21
APPROVED R.S.	06/10/21

BRASSTECH	2001 CARNEGIE AVE. SANTA ANA, CA 92705 (949) 417-5207
INCORPORATED	
SINGLE LIGHT W/LARGE BASE	
DWG NO. 4681L	REV D
SCALE .375	REF. -
SHEET 1	OF 3





BRASSTECH 2001 E. CARNEGIE AVE.
INCORPORATED SANTA ANA, CA 92705
(949) 417-5207

DWG NO.	4681L	REV	D
SCALE	.625	REF.	-
SHEET 3		OF 3	